



REPAIR COST ESTIMATE

K1C228

LOCATION OF DAMAGE PROPERTY: SR 203 Begin MP: 10.70 End MP: 10.70 Dir: Northbound N/B 203	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
-------------------------------------------------------------------------------------------------	-------------------	------------------------------------------

DATE DAMAGE OCCURRED OR OBSERVED: 06/17/2013 OBSERVED	DESCRIPTION OF DAMAGES Guardrail Damage
----------------------------------------------------------	--------------------------------------------

NAME AND ADDRESS OF OWNER: [REDACTED]	NAME AND ADDRESS OF DRIVER: [REDACTED]
------------------------------------------	-------------------------------------------

YEAR, MAKE, TYPE OF VEHICLE: 2007 BMC Sierra	LICENSE: [REDACTED]	DAMAGE TAG:	POLICE DIV: Washington State Patrol	BADGE: 683
-------------------------------------------------	------------------------	-------------	----------------------------------------	---------------

REPAIR COST DISTRIBUTION ESTIMATE

LABOR DESCRIPTION	QTY	REG. HOURS	O/T HOURS	AMOUNT
Maintenance Lead Tech.	1	2.0		\$100.55
Maintenance Tech. 1	1	10.0		\$380.66
Maintenance Tech. 2	4	12.5		\$2,056.07
Maintenance Tech. 3	1	14.0		\$623.21
TOTAL LABOR ESTIMATE:				\$3,160.50

EQUIPMENT TYPE	QTY	HOURS	AMOUNT
0415 - Truck; Flatbed; Extended Cab; Cargo; Diesel	1	14.0	\$129.06
0435 - Truck; 1 Ton; with Dump Body; Extended / Crew Cab; Diesel; with Tommy Lift or Crane	1	13.5	\$150.39
0508 - 1 Ton; Crew Cab; Diesel; 4x4	1	5.0	\$41.48
0825 - Truck; Flatbed; Guardrail Repair; 54,000 GVW; with Knuckle boom Crane	1	14.0	\$164.98
TOTAL EQUIPMENT ESTIMATE:			\$485.93

MATERIAL TYPE	QTY	AMOUNT
Block, Guard Rail Spacer 4"x7 1/2"x14" W-beam For Metal Post King Or Poly Block	10	\$75.42
ET 2000 Extruder Head Terminal	1	\$906.18
Guard Rail, 13' x 6 1/2" Type 31	10	\$1,460.90
Post, Guard Rail Steel 6"x9"x11' - Each	10	\$1,129.14
Post, Guard Rail Steel 6"x9"x8' - Each	1	\$41.24
Post, Guard Rail, 5.5" x 7.5" x 3'9" ET	2	\$66.84
Post, Guard Rail, 6" x 8" x 6' CRT 2 hole	1	\$73.82
TOTAL MATERIAL ESTIMATE:		\$3,753.53



REPAIR COST ESTIMATE

K1C228

LOCATION OF DAMAGE PROPERTY: SR 203 Begin MP: 10.70 End MP: 10.70 Dir: Northbound N/B 203	COUNTY 17 King	DAMAGE CODE 31 Guardrail, Leading End
-------------------------------------------------------------------------------------------------	-------------------	------------------------------------------

MISCELLANEOUS CHARGES - DESCRIPTION	QTY	AMOUNT
		\$0.00
TOTAL MISCELLANEOUS ESTIMATE:		\$0.00

TOTAL CHARGES: \$7,399.96

MAINT. AREA LOCATION: Area 3, Monroe	ORG CODE: 415320	CONT. SECTION A32203	JOB NO: K1C228
SUBMITTED BY: Lois Reitz	DATE: 06/25/2013		
APPROVED BY: Ron Morton	DATE: 06/25/2013	OFFICE USE ONLY: Estimate Only: Y Accident Rpt: E252126 Revised Estimate: N Work Completed: Y Work Completed Date: 06/19/2013	