



## Unassigned Safety Certificate

Certificate Number

**LV - P 064480 9**

It is recommended that this certificate is presented when registering or transferring your vehicle. Until this certificate is presented at a Department of Transport and Main Roads Customer Service Centre, the vehicle registration cannot be transferred online. For more information about online transfers, visit [www.qld.gov.au/onlineregotransfer](http://www.qld.gov.au/onlineregotransfer).

### Vehicle details

Plate number: CYA28X  
State: Queensland  
VIN/Chassis number: 1HGBH41JXMN109186  
Make: TOYOTA MOTOR CORPORATION  
Model: LS400 20 SER  
Body shape: EA  
Series: LX  
Number of cylinders/rotors: 4  
Fuel type: Petrol  
Number of doors: 5  
Engine number: 45578112112  
Compliance type: Compliance Plate  
Date on plate: 1/1997  
Vehicle colour: Silver  
Seating capacity: 5  
Steering position: Centre  
Tare: 3400kg  
GVM: 4500kg

### First inspection - Passed Inspection

#### Odometer reading

43500km

#### Inspection date and time

10:45 am, 16/04/2016

- ✓ Identification
- ✓ Modification Failed/then passed
- ✓ Seats and Restraints
- ✓ Lights and Electrical Components
- ✓ Windscreen and Windows
- ✓ Body and Chassis
- ✓ Steering and Suspension
- ✓ Wheels and Tyres
- ✓ Brakes components
- ✓ Engines and Drivelines
- ✓ Exhaust Emissions
- ✓ Road Test
- ✓ Service Brake Test: Peak - 75%  
Average - 65%
- ✓ Hand brake test: Peak - 85%  
Distance - 8m

### Inspection Station and Examiner details

AIS name: Kmart Tyre & Auto Service  
AIS number: S38393  
AIS address: Shell Coles Express Service Station  
29 Gailey Road  
St Lucia, QLD, 4068

Name of Examiner: B Nash  
Examiner's number: 2383773  
Mobile AIS Rego No: M29332  
Mobile AIS location: 15 Grand Plaza Drv  
Browns Plains, QLD, 4117

- This safety certificate does not need to be displayed on the vehicle offered for sale.
- You must produce this safety certificate for inspection by the prospective buyer or buyer's agent on request.  
Note: Failure to produce this certificate may result in enforcement action.
- This safety certificate is valid for:
  - Licensed Motor Dealers – 3 months/1000km
  - Private Sales – 2 months/2000km

Note: The validity of this safety certificate is determined by whichever occurs first.

- This safety certificate can only be used once for a sale/transfer. (Excluding sales/transfers between licensed motor dealers).
- This certificate or certificate number must be provided to the acquirer of the vehicle at transfer of registration.

**Privacy statement:** The Department of Transport and Main Roads is collecting this information on this form for the purposes of managing the department's vehicle register. This information is authorised or required by the Transport Operations (Road Use Management) Act. The department or its agents usually gives some or all of this information to vehicle insurers, statutory entities, lawyers, insolvency entities, persons involved in vehicle accidents/incidents or vehicle manufacturers or their employees or agents and to or through interstate registration authorities. Your personal details will not be disclosed to any third party without your consent unless required or authorised by law.



## Vehicle details

Plate number: CYA28X  
 State: Queensland  
 VIN/Chassis number: 1HGBH41JXMN109186  
 Make: TOYOTA MOTOR  
 Model: CORPORATION  
 Body shape: LS400 20 SER  
 Series: EA  
 Badge: LX  
 Number of cylinders/rotors: 4  
 Fuel type: Petrol  
 Number of doors: 5  
 Engine number: 45578112112  
 Compliance type: Compliance Plate  
 Date on plate: 1/1997  
 Vehicle colour: Silver  
 Seating capacity: 5  
 Steering position: Right  
 Tare: 3400kg  
 GVM: 4500kg

## Inspection Station and Examiner details

AIS name: Kmart Tyre & Auto Service  
 AIS number: S38393  
 AIS address: Shell Coles Express Service Station, 29 Gailey Road, St Lucia, QLD 4068  
 Name of Examiner: B Nash  
 Examiner's number: 2383773  
 Mobile AIS Rego No: M29332  
 Mobile AIS location: 15 Grand Plaza Drv Browns Plains, QLD, 4117

## First inspection - Failed Inspection

**! Vehicle required for re-inspection within 14 days**

If vehicle is not re-inspected within 14 days a new full inspection including payment is required

### Odometer reading

43500km

### Inspection date and time

10:45 am, 16/04/2016

- ✓ Identification
- ✓ Modification
- ✓ Seats and Restraints
- ✓ Lights and Electrical Components
- ✓ Windscreen and Windows
- ✓ Body and Chassis
- ✓ Steering and Suspension
- ✓ Wheels and Tyres
- ✓ Brakes components
- ✓ Engines and Drivelines
- ✓ Exhaust Emissions
- ✓ Road Test
- ✗ Service Brake Test: Peak - 75%  
Distance - 10m
- ✓ Hand brake test: Peak - 85%  
Average - 70%
- ✗ Details of other items rejected: Exhaust System leaks

### Inspection comments

Excessive brake pedal travel, less than 20% of travel remains

## Details of Failed Inspection

### 1.2 Seat Belts

- 1.2.1 Original manufacturer's seat belts are missing or replacement belts do not meet the vehicle manufacturer's specifications.
- 1.2.5 When extended, the seat belt sash does not retract (the speed of retraction should not be a cause for rejection unless it affects the overall operation of the seat belt assembly in any way).

### 2.7 Battery

- 2.7.3 Batteries fitted in enclosed areas (i.e boot, cabin and so on) are not fitted in a sealed container which is adequately vented to the outside of the vehicle.

### 3.1 Windscreen and Glazing

**Privacy statement:** The Department of Transport and Main Roads is collecting this information on this form for the purposes of managing the department's vehicle register. This information is authorised or required by the Transport Operations (Road Use Management) Act. The department or its agents usually gives some or all of this information to vehicle insurers, statutory entities, lawyers, insolvency entities, persons involved in vehicle accidents/incidents or vehicle manufacturers or their employees or agents and to or through interstate registration authorities. Your personal details will not be disclosed to any third party without your consent unless required or authorised by law.

- 3.1.7 The area of windscreen swept by the wipers to the right of the centre of the vehicle has bull's-eyes or star fractures more than 16mm in diameter or cracks more than 150mm long which either penetrate more than one (1) layer of the glass in a laminated windscreen or interfere with the driver's vision.
- 3.1.10 Anything is fitted to the windscreen or vehicle that obstructs the driver's vision through the swept area of the windscreen.
- 3.1.13 At least half of the number of windows which are designed to be opened, which must include the driver's window, are not capable of being opened.

SAMPLE