



REPAIR ESTIMATE

Phone #

Toll Free #

		_	
Customer Name	LFO INC	Service Advisor	
Year	1993		 •
Make	CHEVROLET	Phone No. 1	
Model	CAMARO	Phone No. 2	
Last 6 VIN	123565		
Mileage	91,097	Fax Number	

QUANTITY	DET.	AILS OF RECOMMENDED REPAIRS	LABOR	PARTS	OTHER
	MSI:-				
	REPAIR STEERING COLUMN -				
	REPLACE LEFT LOWER BALL JOINT			215.00	
	REPLACE FRONT STABILIZER BAR			235.00	
	REPLACE LEFT SIDEVIEW MIRROR			185.00	
	REPLACE DRIVE SHAFT AND CENTER BEARING			900.00	
	MACHINE FRONT BRAKE ROTORS				
	REPLACE WIPER BLADES			35.00	
	OTHERS:- ELECTRIC FUEL PUMP -NOISY				
	WINDOW RATTLES IN DOOR WHEN DOWN				
		Subtotal	750.00	1,570.00	-
		Estimated Shop Supplies			
		Total Estimate	2,320.00		
		Estimated Tax	94.20		
		Total	2,414.20		

The above estimate is based on our inspection and does not include any additional parts or labor which may be required after the work has been started. Occasionally after the repair has started, damaged or broken parts are discovered which are not evident on initial inspection. Estimate prices subject to change after 30 days. Not responsible for any delays caused by unavailability of parts or delays in parts shipment by supplier or transporter. All terms and conditions of repair orders and invoices apply (copy available upon request).